



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
1		22231-4A001 11332247722	BMW/HYUNDAI/LANDROVER/BENZ/MINI/ROVER VALVE LIFTER
2		0903.H2 CRN65BK-RK20	CITROEN/PEUGEOT/FORD/LANDROVER 2.2 HDI ROCKER ARM
3		1336545 1336545	FORD/LANDROVER ROCKER ARM
4		HL6317 LRA06BK-HL00	LANDROVER 09/93-12/98 ATV-35D,36D 38A,39A HYD. LIFT
5		LRA49BK-EV1X	LANDROVER 100 Metro 16V ENGINE VALVE EX.
6		LRA49BK-EV1W	LANDROVER 100 Metro 16V ENGINE VALVE IN.
7		ERC-7151 LR065BK-EV1X0	LANDROVER 109 ENGINE VALVE EX.
8		ERC-7150 LR065BK-EV1W0	LANDROVER 109 ENGINE VALVE IN.




TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
9		NRC-7101,NTC-1888 LR065BK-BJL0	LANDROVER 109 BALL JOINT & LINK
10		607185 LR065BK-FLG0	LANDROVER 109 FLANGE FOR PINION
11		551508/35598 LR019BK-IGS0	LANDROVER 109 IGNITION SWITCH
12		591364 LR065BK-SR10	LANDROVER 109 SYNCHRONIZER RING
13		RTC-5868T LR065BK-TRED	LANDROVER 109 TIE ROD END LH
14		RTC-5867T LR065BK-TREC	LANDROVER 109 TIE ROD END RH
15		HR635 LR065BK-VAS0	LANDROVER 109 VALVE SEAL
16		24G 1345L LR019BK-BL20	LANDROVER 109,110 BARREL LOCK W/KEY



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
17		AEB4324 LR019BK-EB30	LANDROVER 109,110 C/B STD (O/M)
18		AEC4044 LR019BK-B100	LANDROVER 109,110 CAM BUSH
19		NRC-8557,RTC-6399 LR019BK-SU00A	LANDROVER 109,110 DROP ARM (LHD)
20		NRC-8556,RTC-6398 LR019BK-SU00	LANDROVER 109,110 DROP ARM (RHD)
21		STC-1044 LR019BK-SU01	LANDROVER 109,110 DROP ARM W/REPAIR KIT
22		AEM3275 LR019BK-EB10	LANDROVER 109,110 MAIN BEARING STD (O/M)
23		AEU-2761 LR019BK-RK10	LANDROVER 109,110 REPAIR KIT (DROP ARM)
24		STC-1045 LR019BK-SU0D	LANDROVER 109,110 REPAIR KIT DROP ARM LHD



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
25		PRC-5539 LR019BK-TGC0	LANDROVER 109,110 TAILGATE CABLE
26		LU54033732 LR019BK-TSS0	LANDROVER 109,110 TURN SIGNAL SWITCH
27		LU 35292 LR019BK-TSS0A	LANDROVER 109,110 TURN SIGNAL SWITCH(A)
28		PRC-8559A LR019BK-WB10A	LANDROVER 109,110 WIPER BLADE A
29		PRC-8559 LR019BK-WB10	LANDROVER 109,110 WIPER BLADE 12"
30		LU 35302 LR019BK-WPS0	LANDROVER 109,110 WIPER SWITCH
31		ETC-5739 LR066BK-EV1XA	LANDROVER 110 (2.5 D.) ENGINE VALVE EX.
32		ETC-5739 LR066BK-EV1X	LANDROVER 110 (2.5 D.) ENGINE VALVE EX.



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
33		ERR-1230 LR066BK-EV1W	LANDROVER 110 (2.5 D.) ENGINE VALVE IN.
34		ERR-1230 LR066BK-EV1WA	LANDROVER 110 (2.5 D.) ENGINE VALVE IN.
35		FTC 4785 LR066BK-OIS0A	LANDROVER 110 (NEW) OIL SEAL
36		NTC-4260 LR066BK-BJL0	LANDROVER 110 BALL JOINT & LINK
37		76RS LR066BK-BJL0A	LANDROVER 110 BALL JOINT & LINK
38		LR066BK-BCAP	LANDROVER 110 BALL JOINT RUBBER CAP
39		MRC-4473 BT-022	LANDROVER 110 BOLT FOR SPARE TIRE
40		RTC1730 LR066BK-EB31	LANDROVER 110 CON ROD BEARING STD (N/M)




TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
41		AES4575 LR066BK-B030	LANDROVER 110 CON ROD BUSH (N/M)
42		LR066BK-FLG0A	LANDROVER 110 FLANGE
43		FRC 5442 LR066BK-FLG0	LANDROVER 110 FLANGE FRONT OUTPUT
44		ERC-8450 LR066BK-GLP0	LANDROVER 110 GLOW PLUG
45		ETC-8847 LR066BK-GLPA	LANDROVER 110 GLOW PLUG (T.D.I.)
46		ETC-8847 LR066BK-GLPN	LANDROVER 110 GLOW PLUG NEW
47		AEM91896 LR066BK-EB10	LANDROVER 110 MAIN BEARING STD (N/M)
48		RTC2626 LR066BK-EB11	LANDROVER 110 MAIN BEARING STD (N/M)



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
49		ERR 6490 LR066BK-OIS0	LANDROVER 110 OIL SEAL
50		RTC-4198 LR066BK-RK10	LANDROVER 110 REPAIR KIT (BALL JOINT)
51		FRC-5931 LR066BK-SR10	LANDROVER 110 SYNCHRONIZER RING
52		FRC-8232 LR019BK-SR10	LANDROVER 110 SYNCHRONIZER RING
53		FRC 7043 LR066BK-OIS0B	LANDROVER 110 T/BOX OIL SEAL
54		RTC-5870T LR066BK-TRED	LANDROVER 110 TIE ROD END LH
55		RTC-5870GN LR066BK-TREDGN	LANDROVER 110 TIE ROD END LH
56		RTC-5870A LR066BK-TREDA	LANDROVER 110 TIE ROD END LH (ORI. FINISH)



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
57		RTC-5869T LR066BK-TREC	LANDROVER 110 TIE ROD END RH
58		RTC-5869GN LR066BK-TRECGN	LANDROVER 110 TIE ROD END RH
59		RTC-5869A LR066BK-TRECA	LANDROVER 110 TIE ROD END RH (ORI.FINISH)
60		LU 36907 LR066BK-TSS0A	LANDROVER 110 TURN SIGNAL SWITCH
61		STC 439 LR066BK-TSS0	LANDROVER 110 TURN SIGNAL SWITCH
62		452055-4 LR066BK-TCA0	LANDROVER 110/90/DEFENDERTURBO CHARGER ASSY
63		RTC2993 LR241BK-EB30	LANDROVER 12J CON ROD BEARING STD
64		STC3395S LR241BK-EB10	LANDROVER 12J ENGINE MAIN BEARING STD



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
65		CR4208AM LRD28BK-EB40A	LANDROVER 18K16 ENGINE CON ROD BEARING 010
66		CR4208AM LRD28BK-EB30	LANDROVER 18K16 ENGINE CON ROD BEARING STD
67		LR025000/LR025263 LR948BK-TMK0	LANDROVER 2.0L 16V TIMING KIT
68		247583 LR400BK-B030	LANDROVER 2.25 DIESEL CON ROD BUSH
69		ERR2419 LR219BK-B030	LANDROVER 2.5 DIESEL CON ROD BUSH
70		RTC 4778S LR400BK-PTR0	LANDROVER 2.5 DIESEL PISTON RINGS STD
71		LHB101630L LRA08BK-TSB0	LANDROVER 2.5L 24V V6 DOHC 25K4F TENSIONER BEARING
72		LHV100110L LRA08BK-TSB1	LANDROVER 2.5L 24V V6 DOHC 25K4F TENSIONER BEARING



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
73		6Q6211AA LRH64BK-EB40A	LANDROVER 2.7L TDV6 CON ROD BEARING 010
74		6Q6211AA LRH64BK-EB40B	LANDROVER 2.7L TDV6 CON ROD BEARING 020
75		6Q6211AA LRH64BK-EB30	LANDROVER 2.7L TDV6 CON ROD BEARING STD
76		5Q6331AB LRH64BK-EB20A	LANDROVER 2.7L TDV6 MAIN BEARING 010
77		5Q6331AB LRH64BK-EB20B	LANDROVER 2.7L TDV6 MAIN BEARING 020
78		5Q6331AB LRH64BK-EB10	LANDROVER 2.7L TDV6 MAIN BEARING STD
79		SA2415 LRJ53BK-LK20	LANDROVER 216i /416i 1.6L 16V LINER KIT WITH PISTON RING
80		ERR3339 LR187BK-IJT0	LANDROVER 300 TDI INJECTOR



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
81		STC 958 LR187BK-PTR0	LANDROVER 300 TDI PISTON RINGS
82		STC2144 LRO11BK-HVL0	LANDROVER 33, A1, A3 VALVE LIFTER
83		LUL10007 LRL31BK-OSC0	LANDROVER 420 DIESEL CRANKSHAFT SEAL
84		ERR5345 LR547BK-THW0	LANDROVER D50/60/61, TD50/60/61 THRUST WASHER
85		STC442 LR066BK-BBS0	LANDROVER DEFENDER BRAKE BOOSTER
86		SDB00642 LRK82BK-BDC0	LANDROVER DISCOVERY 4.4, V6 PETROL BRAKE DISC (350mm)
87		LR016655 LRA25BK-TSB0	LANDROVER DISCOVERY III 3.0L, 24V, V6 TENSIONER BEARING
88		ERR2640 LR631BK-OIS	LANDROVER ERR 2640 OIL SEAL



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
89		LR000470 LR062BK-BDC0I	LANDROVER FREELANDER 2 3.2 PETROL FRONT BRAKE DISC (316MM)
90		LR001019 LR062BK-BDC0J	LANDROVER FREELANDER 2 REAR BRAKE DISC (302MM)
91		LFB 00015010L LR062BK-EB30B	LANDROVER FREELANDER C/R BRG BLUE
92		LFB 00015020L LR062BK-EB30R	LANDROVER FREELANDER C/R BRG RED
93		LFB00015030L LR062BK-EB30Y	LANDROVER FREELANDER C/R BRG YELLOW
94		WAM 402610L LR062BK-EB10LB	LANDROVER FREELANDER M/B LOWER BLUE
95		WAM 402630L LR062BK-EB10LG	LANDROVER FREELANDER M/B LOWER GREEN
96		WAM 402620L LR062BK-EB10LR	LANDROVER FREELANDER M/B LOWER RED



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
97		WAM 402710L LR062BK-EB10UB	LANDROVER FREELANDER M/B UPPER BLUE
98		WAM 402730L LR062BK-EB10UG	LANDROVER FREELANDER M/B UPPER GREEN
99		WAM 402720L LR062BK-EB10UR	LANDROVER FREELANDER M/B UPPER RED
100		0100226129 LR061BK-GLP0	LANDROVER GLOW PLUG
101		WAM2492L LR041BK-THW0	LANDROVER K ENGINE 1.8 THRUST WASHER STD
102		IX123 LRC31BK-RGL0	LANDROVER MARELLI IR/IF ALTERNATOR REGULATOR (12 Volt, A-Circuit, 14.1 Vset)
103		70992880 LR281BK-TSB0	LANDROVER RANGE, WAGON, ROVER MKII TENSIONER BEARING
104		LR024999 LR305BK-CSG1	LANDROVER RANGER 2.0 CAMSHAFT GEAR



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
105		LR025628 LR305BK-CSG0	LANDROVER RANGER 2.0L CAMSHAFT GEAR
106		1311306 LR305BK-TSBP	LANDROVER RANGER 2.7L 24V V6 TENSIONER BEARING PULLEY
107		LR000571 LR305BK-BDC0	LANDROVER RANGER ROVER EVOQUE 2.2 TD4 BRAKE DISC (300MM)
108		1324388 LR305BK-TSB0	LANDROVER RANGER, DISCOVERY III (2.7L, 24V, V6) TENSIONER BEARING
109		SDB000622 LRA27BK-BDC0I	LANDROVER SPORT 4.2, 4.4 V8 FRONT BRAKE DISC (360mm)
110		BHM1592L LR762BK-THW0	LANDROVER TD 2.0THRUST WASHER
111		LR000660 LRA36BK-TSBP0	LANDROVER TD4 (2.2L, 16V, L4) TENSIONER BEARING PULLEY
112		LEB000610 LR041BK-EB30LB	LANDROVER TD4 CON ROD BEARING STD LOWER BLUE










TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
113		LFB000050 LR041BK-EB30UB	LANDROVER TD4 CON ROD BEARING UPPER BLUE STD
114		LEB102250L LR041BK-EB21ALY	LANDROVER TD4 FLANGE MAIN BEARING 0.25 LOWER YELLOW
115		LEB102140L LR041BK-EB21AUY	LANDROVER TD4 FLANGE MAIN BEARING 0.25 UPPER YELLOW
116		LEB102210L LR041BK-EB11LY	LANDROVER TD4 FLANGE MAIN BEARING STD LOWER YELLOW
117		LEB102110L LR041BK-EB11UY	LANDROVER TD4 FLANGE MAIN BEARING STD UPPER YELLOW
118		LEB000120 LR041BK-EB10LY	LANDROVER TD4 MAIN BEARING STD LOWER YELLOW
119		LEB000060 LR041BK-EB10UY	LANDROVER TD4 MAIN BEARING STD UPPER YELLOW
120		LR009395 LRA36BK-TSBP	LANDROVER TD4, SD4 (2.2L, 16V, L4) TENSIONER BEARING PULLEY



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
121		STC3300 LR547BK-EB30	LANDROVER TD5 ENGINE C/R BEARING STD
122		STC3299 LR547BK-EB10	LANDROVER TD5 ENGINE MAIN BEARING STD
123		LEB 101060L LR948BK-EB10	LANDROVER TICE 2.0 DIESEL M/BEARING STD
124		STC 3724 LR770BK-EB10	LANDROVER V8 3.9 DIESEL MAIN BEARING STD
125		LEB000360 LR770BK-EB41ALR	LANDROVER V8 4.4 CON ROD BEARING 0.25 LOWER RED
126		LEB000340 LR770BK-EB31LR	LANDROVER V8 4.4 CON ROD BEARING STD LOWER RED
127		LEB000350 LR770BK-EB31UB	LANDROVER V8 4.4 CON ROD BEARING STD UPPER BLUE
128		LEB000270 LR770BK-EB21ALY	LANDROVER V8 4.4 DIESEL MAIN BEARING 0.25 LOWER YELLOW



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
129		LEB000240 LR770BK-EB21AUY	LANDROVER V8 4.4 DIESEL MAIN BEARING 0.25 UPPER YELLOW
130		LEB000180 LR770BK-EB11LY	LANDROVER V8 4.4 DIESEL MAIN BEARING STD LOWER YELLOW
131		LEB000210 LR770BK-EB11UY	LANDROVER V8 4.4 DIESEL MAIN BEARING STD UPPER YELLOW
132		LXC000010L LRC78BK-RK20	LANDROVER X5 ROCKER ARM
133		LR004167 LRI29BK-RK20	LANDROVER XF ROCKER ARM
134		1450604 LRA49BK-HVL0	LANDROVER/CITROEN/FIAT/LANCIA/PEUGEOT/ FORD/MITSUBISHI/LANCIA 2.2L 16V, L4 HYD.VALVE LIFTER
135		1025392 LRC57BK-HVL0	LANDROVER/FORD/GENERAL MOTORS 4.0L 24V V6 HYD.VALVE LIFTER
136		LGR100340L LGR100340	LANDROVER/MG/ROVER HYD. VALVE LIFTER



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

LANDROVER CATALOGUE

Date: 2023/11/03

SEQ.	PHOTO	OEM_NO/ITEM_NO	DESCRIPTION
137		LGR100100 LGR1000050	LANDROVER/MG/ROVER VALVE LIFTER