











TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|--------------------------------|---|
| 1 |  | 4410321030□ FR058BK-ABS7 | FORD, FREIGHTLINER, HINO, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR |
| 2 |  | 4410328130□ FR058BK-ABS6 | FORD, FREIGHTLINER, HINO, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 67, L: 1702mm) |
| 3 |  | 5C4Z-2C204-EA□ FD058BK-ABS4 | FORD, FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (L:1092MM) |
| 4 |  | 801551□ FD058BK-ABS0 | FORD, FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 43, L: 1092mm) |
| 5 |  | 800198□ FD058BK-ABS3 | FORD, FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 50, L: 1270mm) |
| 6 |  | 5001325□ FD058BK-ABS2 | FORD, FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 63, L: 1600mm) |
| 7 |  | 800715□ FD058BK-ABS1 | FORD, FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 63, L: 1600mm) |
| 8 |  | 4410328090□ FR058BK-ABS9 | FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 39, L: 1000mm) |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|------------------------------------|---|
| 9 |  | 4410329190□ FR058BK-ABS8 | FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 69 L: 1753mm) |
| 10 |  | 364098081□ FR058BK-ABS0 | FREIGHTLINER, MACK, NAVISTAR, VOLVO TRUCK ABS SENSOR (In.: 98, L: 2489mm) |
| 11 |  | AL1027196□ FR058BK-ABS3 | FREIGHTLINER, MACK, VOLVO TRUCK ABS SENSOR (In.: 20, L: 508mm) |
| 12 |  | 801541□ FR058BK-ABS2 | FREIGHTLINER, MACK, VOLVO TRUCK ABS SENSOR (In.: 66, L: 1676mm) |
| 13 |  | 4410328140□ FR058BK-ABS4 | FREIGHTLINER, MACK, VOLVO TRUCK ABS SENSOR (In.: 79, L: 2007mm) |
| 14 |  | 6I-3310 / 1253725□ JDD82BK-TSB0 | JOHN DEERE 450H/550H/650H, CATERPILLAR, CUMMINS, MACK TENSIONER BEARING |
| 15 |  | 25195022□ MKB02BK-TSB0 | MACK 513 TENSIONER BEARING |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|--|---------------------------------|
| 16 |  | <input type="checkbox"/> 2894-195300023 | MACK CABLE |
| 17 |  | <input type="checkbox"/> 25175065 | MACK CLUTCH CABLE |
| 18 |  | <input type="checkbox"/> MK058BK-MR0A0C | MACK CV713 MIRROR ASSEMBLY RH |
| 19 |  | <input type="checkbox"/> MK058BK-MR0A1C | MACK CV713 MIRROR ASSEMBLY RH |
| 20 |  | <input type="checkbox"/> MK058BK-MR0A2C | MACK CV713 MIRROR ASSEMBLY RH |
| 21 |  | <input type="checkbox"/> MK058BK-MR0A3C | MACK CV713 MIRROR ASSEMBLY RH |
| 22 |  | 215SB72P <input type="checkbox"/> MK993BK-EB10 | MACK DE6 E6 MAIN BEARING STD |
| 23 |  | 215SB72C <input type="checkbox"/> MKJ31BK-EB20A | MACK E6 ENGINE MAIN BEARING 010 |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|----------------------------|---|
| 24 |  | 215SB72C□ MKJ31BK-EB10 | MACK E6 ENGINE MAIN BEARING STD |
| 25 |  | 315GC445G□ MKJ31BK-OP10 | MACK E6 OIL PUMP ASSY |
| 26 |  | A60010□ MKJ31BK-PTR0 | MACK E6 PISTON RINGS 123.83mm |
| 27 |  | 446GC279□ MKJ31BK-VAS0 | MACK E6 VALVE SEAL |
| 28 |  | 57GC189□ MKJ31BK-GT30 | MACK E6 2 VALVE MODEL CYL HEAD GASKET |
| 29 |  | □ MKJ31BK-PTN1F | MACK E6 PISTON/PIN/CLIP 2ALFIN (Bore: 123.83mm) |
| 30 |  | 62GB2396□ MKJ01BK-EB30 | MACK E7 ENGINE CON ROD BEARING STD |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|----------------------------|--|
| 31 |  | 322GC45□ MK058BK-FP10 | MACK E7 FUEL PUMP |
| 32 |  | 64MT2103□ MKJ01BK-TSN0 | MACK E7 TEMPERATURE SENSOR |
| 33 |  | 57GC2144□ MKJ01BK-THW0 | MACK E7 THRUST WASHER STD |
| 34 |  | 215SB231A□ MKJ01BK-PTN0 | MACK E7 E-TECH (EUP) PISTON/PIN/CLIP 2PCS TYPE (Bore: 123.83mm) |
| 35 |  | 509GC463□ MKJ01BK-EL10 | MACK E7 E-TECH (EUP), PLN (12.1L) ENGINE LINER STD (123.83 mm) |
| 36 |  | 57GC2115A□ MKJ01BK-GT31 | MACK E7 PLN MODEL CYL HEAD GASKET |
| 37 |  | □ MKJ01BK-PTN1 | MACK E7 PLN PISTON/PIN/CLIP/PIN BUSH 2PCS TYPE WITH (Bore: 123.83mm) |
| 38 |  | □ MK993BK-RIV0 | MACK ENDT/ENDLT/ETAB/ETAY/ETAZB RIVET |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|-----------------------------|---|
| 39 |  | MB-1373W□ MK993BK-THW0 | MACK ENDT673/C THRUST WASHER STD |
| 40 |  | □ 25152850 | MACK HOOD CONTROL CABLE |
| 41 |  | □ 25171452 | MACK HOOD COTROL CABLE |
| 42 |  | □ 25171709 | MACK HOOD COTROL CABLE |
| 43 |  | 21746206□ MKI99BK-OLS0 | MACK MP / VOLVO D12, D13 OIL PAN PRESSURE SENSORS |
| 44 |  | 205130379□ MKL44BK-GT40U | MACK MP8 GASKET UPPER SET |
| 45 |  | □ MKL44BK-PTN0 | MACK MP8 PISTON/PIN/CLIP 133mm |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|--------------------------------|--|
| 46 |  | 21293367□ MKL44BK-GT20 | MACK MP8 / VOLVO FM13 OIL PAN GASKET |
| 47 |  | 87GB45□ MK058BK-TSB1 | MACK RENAULT TRUCK TENSIONER BEARING |
| 48 |  | □ MKK62BK-BKC0 | MACK T30/30DD 4-STUD SPRING BRAKE CHAMBER (FLAT COVER) YELLOW |
| 49 |  | 9111535400□ MK058BK-ACS0 | MACK TRUCK AIR COMPRESSOR |
| 50 |  | 2104-10893551□ MK058BK-CLK0 | MACK TRUCK CLUTCH KIT |
| 51 |  | 22923707□ MK058BK-IDP0 | MACK TRUCK IDLER PULLEYS |
| 52 |  | 3QM313M□ MK058BK-LAC0 | MACK TRUCK LATCH |
| 53 |  | 062-1094-00□ MK058BK-LSGI | MACK TRUCK LEAF SPRING FRONT |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|-----------------------------|---|
| 54 |  | 4QK4005A□ MK058BK-LSGJ | MACK TRUCK LEAF SPRING REAR |
| 55 |  | 54341□ MK058BK-LVV0 | MACK TRUCK LEVELING VALVE |
| 56 |  | 87GB46□ MK058BK-TSB0 | MACK TRUCK TENSIONER BEARING |
| 57 |  | 87GB33□ MK058BK-TSB3 | MACK TRUCK TENSIONER BEARING |
| 58 |  | 316GC1184J□ MK058BK-WP00 | MACK TRUCK WATER PUMP |
| 59 |  | 87GB41□ MK058BK-TSB2 | MACK TRUCK TENSIONER BEARING |
| 60 |  | 4497130180□ MK058BK-ABS5 | MACK, FREIGHTLINER, NAVISTAR, VOLVO TRUCK ABS SENSOR (L:1829MM) |











TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|------------------------------|--|
| 61 |  | R955608 □ MK058BK-ABS4 | MACK, NAVISTAR TRUCK ABS SENSOR (L:2060MM) |
| 62 |  | 4497130500 □ MK058BK-ABS3 | MACK/NAVISTAR/VOLVO/FREIGHTLINER TRUCK ABS SENSOR |
| 63 |  | 8945900692 □ MK058BK-ABS2 | MACK/NAVISTAR/VOLVO/FREIGHTLINER TRUCK ABS SENSOR (L:3048MM) |
| 64 |  | 065640 □ NT058BK-ABS1 | NAVISTAR / FREIGHTLINER / MACK / PACCAR / VOLVO TRUCK ABS SENSOR (In.: 66, L: 1680mm) |
| 65 |  | 745801542 □ NT058BK-ABS0 | NAVISTAR, FREIGHTLINER, MACK, VOLVO TRUCK ABS SENSOR (In.: 79, L: 2007mm) |
| 66 |  | AL919803 □ NT058BK-BSR0 | NAVISTAR/ FREIGHTLINER/MACK TRUCK ABS BRAKE SENSOR (IN:79, L:2007MM) |
| 67 |  | AL919801 □ NT058BK-BSR1 | NAVISTAR/FREIGHTLINER/MACK TRUCK ABS BRAKE SENSOR (IN:40, L:1016MM) |
| 68 |  | AL919804 □ NT058BK-BSR4 | NAVISTAR/MACK/FREIGHTLINER TRUCK ABS BRAKE SENSOR (L:2515MM) |



TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|-------|------------------------------|---|
| 69 | | AL919802□ NT058BK-BSR3 | NAVISTAR/MACK/FREIGHTLINER TRUCK ABS BRAKE SENSOR (L:1524MM) |
| 70 | | 801538□ PC058BK-ABS1 | PACCAR / FREIGHTLINER / MACK / NAVISTAR / VOLVO TRUCK ABS SENSOR (In.: 76, L: 1930mm) |
| 71 | | 4410329710□ PC058BK-ABS0 | PACCAR / FREIGHTLINER / MACK / NAVISTAR / VOLVO TRUCK ABS SENSOR (In.: 81, L: 2057mm) |
| 72 | | 270 950-9□ VV542BK-LRK0Z | VOLVO (TD122F) FH12/ NH12/ FM12/ N23/ NL12/ TD16 / MACK MP8 LINER RING KIT N/M |
| 73 | | 20508011□ VV058BK-PFS0 | VOLVO / MACK TRUCK SPEED SENSOR |
| 74 | | 63038□ VV058BK-SDS3 | VOLVO / MACK TRUCK FH12 SPEED SENSOR (OIL PRESSURE SENSOR) |
| 75 | | 7421819687□ VV058BK-TSB12 | VOLVO MACK CAT TRUCK TENSIONER BEARING |





TECNOPART INTERNATIONAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei,Taiwan,R.O.C.

TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: tecno.part@msa.hinet.net

CATALOGUE

Date: 2023/11/01

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|---------------------------|--|
| 76 |  | 21454379□ VV543BK-TSB0 | VOLVO MACK D11, DS11 TENSIONER BEARING |
| 77 |  | 20582558□ VV058BK-TSB8 | VOLVO VN / MACK TENSIONER BEARING |